



Inspection Photos
well 107-06142
Pit 117433
REM # 30484
Inspection
Date:8/3/2023

All Photos taken
by Kris Neidel

Photo #1 a Backhoe was used to sample below the old tank battery. It appeared that soil was contaminated (per smell, PID and appearance) to depth excavated, aprox 30". The location will need delineation via a rig capable of dealing with the rocky soils.



Inspection Photos
well 107-06142
Pit 117433
REM # 30484
Inspection
Date:8/3/2023

All Photos taken
by Kris Neidel

Photo #2 view what is believed to be an old pad of the Bear Victor 4-13, 107-06145.



Photo #3 A second test pit was dug to see if observed contamination in the first pit extended. It appears that contamination exists below the entire foot print of tank battery.

Inspection Photos
well 107-06142
Pit 117433
REM # 30484
Inspection
Date:8/3/2023

All Photos taken
by Kris Neidel



Inspection Photos
well 107-06142
Pit 117433
REM # 30484
Inspection
Date:8/3/2023

All Photos taken
by Kris Neidel

Photo #4 a sample was collected of apparent contamination at Tank Battery. Note: center of photo is where sample was collected (orange circle).



Inspection Photos
well 107-06142
Pit 117433
REM # 30484
Inspection
Date:8/3/2023

All Photos taken
by Kris Neidel

Photo #5 close of soil from photo #4



Inspection Photos
well 107-06142
Pit 117433
REM # 30484
Inspection
Date:8/3/2023

All Photos taken
by Kris Neidel

Photo #6 The plate welded to the well bore was exposed via excavation. Samples were collected below the plate.



Photo #7 Flowlines that remain. The are going from the Pad to the east to the pit, facility #117433.

**Inspection Photos
well 107-06142
Pit 117433
REM # 30484
Inspection
Date:8/3/2023**

**All Photos taken
by Kris Neidel**



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



**Photo #8 Bayless
contractor collecting
hand augured sample
from pit # 30484**

**Inspection Photos
well 107-06142
Pit 117433
REM # 30484
Inspection
Date:8/3/2023**

**All Photos taken
by Kris Neidel**



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



**Photo #9 piping
remains at pit**

**Inspection Photos
well 107-06142
Pit 117433
REM # 30484
Inspection
Date:8/3/2023**

**All Photos taken
by Kris Neidel**



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



**Photo #10 pile of
soil in upper of
photo was where
rig anchor was
removed at
northeast side of
pad.**

**Inspection Photos
well 107-06142
Pit 117433
REM # 30484
Inspection
Date:8/3/2023**

**All Photos taken
by Kris Neidel**



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos
well 107-06142
Pit 117433
REM # 30484
Inspection
Date:8/3/2023

All Photos taken
by Kris Neidel

Photo #11 piping remains at Pit.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources