

Final Reclamation and Stormwater Inspection

Date: 08/09/2023

Operator: MOUNTAIN PETROLEUM CORP - 60890

Location ID: 410482

Inspection Document #: 708200454

Yuma County, CO

CNE Section 9 T5N R45W

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Fitch 1-9
Location ID: 410482



Photo 1. Facing west at the former well location. The reclaimed portion is currently in fallow cropland comprised of wheat stubble and annual weeds. Staff was unable to verify vegetative compliance at the time of this inspection, therefore, it is being left “In Process” until it can be inspected at a future date to verify crop establishment in accordance with Rule 1004 regulations and standards.