

Final Reclamation and Stormwater Inspection

Date: 08/09/2023

Operator: ROSEWOOD RESOURCES INC - 75027

Location ID: 303013

Inspection Document #: 708200470

Yuma County, CO

NESW Section 35 T3N R47W

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources



Photo 1. Road base/gravel remains on the former access road and will need to be removed per Rule 1004 regulations and standards.



Photo 2. The former location will need to be leveled/graded as there was evidence of contouring issues at the time of this inspection (highlighted in red).

Inspection Photos
Location Name: Lott 1-35
Location ID: 303013



8/9/23, 3:07 PM
113° SE
COGCC

Photo 3. See comments in Photo 2.

Inspection Photos
Location Name: Lott 1-35
Location ID: 303013



Photo 4. The former well location does not appear to be progressing towards Rule 1004 reclamation standards. Evidence of bare/exposed soil was observed, possibly a result of compaction issues or soil suitability exceedances. Further soil investigation and/or reclamation activities are required.