

**Storm Water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC N36NWB Pad**  
**Location #: 334967**



**Location Overview: Location is within High  
Priority/Density/Black Bear Habitat areas.**  
**Section/Township/Range: 36 6S93W**



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC N36NWB Pad**  
**Location #: 334967**



**North West corner of location.**



**North East corner of location.**



**South West corner of location.**



**South East corner of location.**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC N36NWB Pad**  
**Location #: 334967**



**Photo # 5977 Rill erosion along ditch**



**Photo # 5978 Erosion & transport of sediment/insufficient runoff controls/BMP's (NE area of location near entrance to ditch that runs off location)**

**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC N36NWB Pad**  
**Location #: 334967**



**Photo # 5979 Erosion & transport of sediment/insufficient runoff controls/BMP's (NE area of location at beginning of ditch that runs off location)**



**Photo # 5981 Rill erosion along ditch**