

**KT Resources LLC  
Ant Hill County 25-12  
Loc ID: 316336**



**When sign is replaced additional information required**



**Soil staining from separator**



KT Resources LLC  
Ant Hill County 25-12  
Loc ID: 316336




**Stained soils**



**Stained soil**



KT Resources LLC  
Ant Hill County 25-12  
Loc ID: 316336



Gas meter calibration overdue



No Stormwater BMP



**KT Resources LLC  
Ant Hill County 25-12  
Loc ID: 316336**



**No Stormwater BMP**



**Leaking equipment. Stained soil**



**KT Resources LLC  
Ant Hill County 25-12  
Loc ID: 316336**



**Inadequate tank berm**



**Tank berm inadequate**



**KT Resources LLC  
Ant Hill County 25-12  
Loc ID: 316336**



**Lack of Stormwater BMPs**



**When sign is replaced additional information is required**



**KT Resources LLC  
Ant Hill County 25-12  
Loc ID: 316336**




**Lack of stormwater BMP**



**Stormwater BMPs ineffective**



**KT Resources LLC  
Ant Hill County 25-12  
Loc ID: 316336**



**Location from Southwest corner**



**Location from Southeast corner**



**KT Resources LLC  
Ant Hill County 25-12  
Loc ID: 316336**



**Location from Northeast corner**



**Location from Northwest corner**