

Inspection Photos
Location Name: Bledsoe 3-26-5-45
API Number: 125-09642



1. Well sign.



2. View of wellhead.

Inspection Photos
Location Name: Bledsoe 3-26-5-45
API Number: 125-09642



3. View of removed bent tubing joint where the tubing had split allowing the well to vent uncontrolled.



4. View of unused equipment and debris still at well location.