

Inspection Photos

Location Name: GUNNISON ENERGY LLC, DGU Federal 1289/Section 18 Pad

Location ID: 427218

Date: 8/14/2023



NE Corner of Location – Photo #05816



NW Corner of Location – Photo #05817

Inspection Photos

Location Name: GUNNISON ENERGY LLC, DGU Federal 1289/Section 18 Pad

Location ID: 427218

Date: 8/14/2023



SW Corner of Location – Photo #05818



SE Corner of Location – Photo #05819

Inspection Photos

Location Name: GUNNISON ENERGY LLC, DGU Federal 1289/Section 18 Pad

Location ID: 427218

Date: 8/14/2023



Separator – Photo #05824



Separators – Photo #05825

Inspection Photos

Location Name: GUNNISON ENERGY LLC, DGU Federal 1289/Section 18 Pad

Location ID: 427218

Date: 8/14/2023



Tank Battery – Photo #05831



Open-Ended Hose – Photo #05828

Inspection Photos

Location Name: GUNNISON ENERGY LLC, DGU Federal 1289/Section 18 Pad

Location ID: 427218

Date: 8/14/2023



Open-Ended Hose – Photo #05829




Damaged Berm Liner – Photo #05827

Inspection Photos

Location Name: GUNNISON ENERGY LLC, DGU Federal 1289/Section 18 Pad

Location ID: 427218

Date: 8/14/2023



Location Lacks Stabilization – Photo #05832

**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #05833**

Inspection Photos

Location Name: GUNNISON ENERGY LLC, DGU Federal 1289/Section 18 Pad

Location ID: 427218

Date: 8/14/2023



Unprotected Soil Stockpile – Photo #05884



Unprotected Soil Stockpile – Photo #05881

Inspection Photos

Location Name: GUNNISON ENERGY LLC, DGU Federal 1289/Section 18 Pad

Location ID: 427218

Date: 8/14/2023



Unprotected Soil Stockpile – Photo #05882



Unprotected Soil Stockpile – Photo #05879