

## Inspection Photos

Location Name: SG INTERESTS I LTD, FEDERAL-611S90W/24SWNE

Location ID: 324480

Date: 8/14/2023



SE Corner of Location – Photo #05841



SW Corner of Location – Photo #05842

## Inspection Photos

Location Name: SG INTERESTS I LTD, FEDERAL-611S90W/24SWNE

Location ID: 324480

Date: 8/14/2023



**NW Corner of Location – Photo #05843**



**NE Corner of Location – Photo #05844**



## Inspection Photos

Location Name: SG INTERESTS I LTD, FEDERAL-611S90W/24SWNE

Location ID: 324480

Date: 8/14/2023



Wellhead – Photo #05845



Separator – Photo #05846



## Inspection Photos

Location Name: SG INTERESTS I LTD, FEDERAL-611S90W/24SWNE

Location ID: 324480

Date: 8/14/2023



**Tank Battery – Photo #05847**



**Lease Road Washing Out/Insufficient Erosion Controls – Photo #05876**

## Inspection Photos

Location Name: SG INTERESTS I LTD, FEDERAL-611S90W/24SWNE

Location ID: 324480

Date: 8/14/2023



**Rill Erosion on Lease Road/Insufficient Erosion Control –  
Photo #05877**