

Inspection Photos

Location Name: SG INTERESTS I LTD, FEDERAL 11-90-24-611S90W/24NWSE

Location ID: 324469

Date: 8/14/2023



SE Entrance to Location – Photo #05853



NE Corner of Location – Photo #05854

Inspection Photos

Location Name: SG INTERESTS I LTD, FEDERAL 11-90-24-611S90W/24NWSE

Location ID: 324469

Date: 8/14/2023



NW Corner of Location – Photo #05855



SW Corner of Location – Photo #05856

Inspection Photos

Location Name: SG INTERESTS I LTD, FEDERAL 11-90-24-611S90W/24NWSE

Location ID: 324469

Date: 8/14/2023



Wellhead – Photo #05857



Separator – Photo #05860

Inspection Photos

Location Name: SG INTERESTS I LTD, FEDERAL 11-90-24-611S90W/24NWSE

Location ID: 324469

Date: 8/14/2023



Tank Battery – Photo #05861



Storage of Unused Supplies/Equipment – Photo #05859

Inspection Photos

Location Name: SG INTERESTS I LTD, FEDERAL 11-90-24-611S90W/24NWSE

Location ID: 324469

Date: 8/14/2023



Insufficient Erosion Control/Road Washing Out – Photo #05876



Rill Erosion Cutting Through Lease Road – Photo #05877