

Inspection Photos

Location Name: SG INTERESTS I LTD, Cow Skull 11-89-18/1

Location ID: 414132

Date: 8/14/2023



East Entrance to Location – Photo #05864



SW Corner of Location – Photo #05865

Inspection Photos


Location Name: SG INTERESTS I LTD, Cow Skull 11-89-18/1

Location ID: 414132

Date: 8/14/2023



NW Corner of Location – Photo #05866




Wellheads – Photo #05869

Inspection Photos

Location Name: SG INTERESTS I LTD, Cow Skull 11-89-18/1

Location ID: 414132

Date: 8/14/2023



Separators – Photo #05867



Tank Battery – Photo #05868

Inspection Photos

Location Name: SG INTERESTS I LTD, Cow Skull 11-89-18/1

Location ID: 414132

Date: 8/14/2023



Lease Road Degradation – Photo #05870



Rill Erosion Cutting Through Lease Road – Photo #05871

Inspection Photos

Location Name: SG INTERESTS I LTD, Cow Skull 11-89-18/1

Location ID: 414132

Date: 8/14/2023



Rill Erosion Cutting Through Lease Road – Photo #05872



Unprotected Soil Stockpile – Photo #05873

Inspection Photos

Location Name: SG INTERESTS I LTD, Cow Skull 11-89-18/1

Location ID: 414132

Date: 8/14/2023



Unprotected Soil Stockpile – Photo #05874