

Inspection Photos

API: 071-09540

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 8/16/2023



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 071-09540 | Date: 8/16/2023

Inspection Photos



Photo 1. Facing south toward the access road.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API: 071-09540 | Date: 8/16/2023

Inspection Photos



Photo 2. Facing southeast toward the well site.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 3. Facing south at the location.



Inspection Photos



Photo 4. There are oily fluids in the engines skid that needs to be cleaned up.



Inspection Photos



Photo 5. Facing northwest along the fill slope which is stabilized with perennial vegetation.

