

## Inspection Photos

Location Name: Wayne/5N64W22 1-10

Location ID: 329128



**Photo #1**

**Wayne/5N64W22 1-10 pad**

10: Wellsites

**Producing | PR**

*NW → SE*



**Photo #2**

**Wayne 01N (123-45980) Wellsite**

**Producing | PR**




**COLORADO**

**Energy & Carbon Management  
Commission**


Department of Natural Resources

**Inspection Photos**  
**Location Name: Wayne/5N64W22 1-10**  
**Location ID: 329128**



**Photo #3**

**Wayne 02N (123-45977) Wellsite**  
**Producing | PR**




**Photo #4**

**Wayne 03C (123-45976) Wellsite**  
**Producing | PR**



**Inspection Photos**  
**Location Name: Wayne/5N64W22 1-10**  
**Location ID: 329128**



**Photo #5**

**Wayne 04N (123-45981) Wellsite**  
**Producing | PR**



**Photo #6**

**Wayne 05N (123-45975) Wellsite**  
**Producing | PR**




**COLORADO**  
**Energy & Carbon Management**  
**Commission**  
Department of Natural Resources

**Inspection Photos**  
**Location Name: Wayne/5N64W22 1-10**  
**Location ID: 329128**



**Photo #7**  
**Wayne 06N (123-45979) Wellsite**  
**Producing | PR**



**Photo #8**  
**Wayne 07N (123-45982) Wellsite**  
**Producing | PR**



**Inspection Photos**  
**Location Name: Wayne/5N64W22 1-10**  
**Location ID: 329128**



**Photo #9**

**Wayne 08N (123-45973) Wellsite**  
**Producing | PR**



**Photo #10**

**Wayne 09N (123-45978) Wellsite**  
**Producing | PR**



## Inspection Photos

Location Name: Wayne/5N64W22 1-10

Location ID: 329128



**Photo #11**

**Wayne 10N (123-45974) Wellsite**

**Producing | PR**



**Photo #12**

**Wayne/5N64W22 1-10 pad**

**Battery site**

**Active**

***Equipment Documented; Loc ID: 329128***



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources