

Inspection Photos

Location Name: Loloff Farms/5N64W26I

Location ID: 439606



Photo #1

Loloff Farms/5N64W26I pad

Wellsite(s): 4

3: Producing | PR

1: Shut-In | SI

E → W




Photo #2

Loloff Farms 26I-402 (123-40516) Wellsite

Shut-In | SI



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Loloff Farms/5N64W26I

Location ID: 439606



Photo #3

Loloff Farms 26I-312 (123-40513) Wellsite

Producing | PR



Photo #4

Loloff Farms 26H-232 (123-40510) Wellsite

Producing | PR



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Loloff Farms/5N64W26I

Location ID: 439606



Photo #5

Loloff Farms 26H-332 (123-40514) Wellsite

Producing | PR



Photo #6

Loloff Farms/5N64W26I pad

Battery site

Active

Equipment Documented; Loc ID: 439606



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources