

Inspection Photos

Location Name: Loloff Farms/5N64W26I

Location ID: 439606



Photo #1

Loloff Farms/5N64W26I pad

Battery site

Active



Photo #2

Loloff Farms/5N64W26I pad

Battery site

Active

Tank(s): SE corner



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Loloff Farms/5N64W26I
Location ID: 439606



Photo #3
Loloff Farms/5N64W26I pad
Battery site
Active
ECD(s)



Photo #4
Loloff Farms/5N64W26I pad
Battery site
Active
Separator(s), VRU(s)



Inspection Photos
Location Name: Loloff Farms/5N64W26I
Location ID: 439606



Photo #5
Loloff Farms/5N64W26I pad
Battery site
Active
LACT




Photo #6
Loloff Farms/5N64W26I pad
Battery site
Active
Battery sign



Inspection Photos

Location Name: Loloff Farms/5N64W26I

Location ID: 439606



Photo #7

Loloff Farms/5N64W26I pad

Wellsite(s): 4

3: Producing | PR

1: Shut-In | SI

Well names / API: documented on FIR doc #707601691.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources