

## Attachment B



<b>SITE NAME:</b> WIEDEMAN 33-21U Wellhead							<b>DATE:</b> 6/7/2023	<b>REM. PROJECT #:</b> 28650	<b>WEATHER:</b> 70S SUNNY			
<b>SITE DIRECTIONS:</b> CR 56 and 113th Ave, south 1 mile							<b>CLIENT:</b> PDC					
<b>LEGALS AND LAT/LONG:</b> 40.383360, -104.895420							<b>TASMAN PERSONNEL:</b> JORDAN HESTMARK					
<b>SOIL TYPES:</b> Silty Sand - SM							<b>SURFACE GRADIENT:</b> South					
<b>SOIL SAMPLING</b>							<b>FACILITY INFRASTRUCTURE</b>					
Date/Time	Soil Sample ID	PID (ppm)	Visual	Olfactory	Photo?	Grab or Lab Sample?	EQUIPMENT		Quantity			
							Above Ground Storage Tank (AST)					
6/7/2023 13:54	FL01-01 @ 4'	0.0	No Staining	No Odor	Yes	Grab	Buried or Partially Buried Vessel					
6/7/2023 13:51	FL01-02 @ 4'	0.2	No Staining	No Odor	Yes	Grab	Separator					
6/7/2023 13:48	FL01-03 @ 4'	0.0	No Staining	No Odor	Yes	Grab	Emission Control Device (ECD)					
6/7/2023 13:39	FL01-04 @ 4'	0.0	No Staining	No Odor	Yes	Lab	Dump Line					
6/7/2023 13:33	FL01-05 @ 4'	0.2	No Staining	No Odor	Yes	Grab	Wellhead		1			
6/7/2023 13:25	FL01-06 @ 4'	0.1	No Staining	No Odor	Yes	Grab	Flowline		1			
6/7/2023 13:20	FL01-07 @ 4'	0.1	No Staining	No Odor	Yes	Lab	Other:					
6/9/2023 10:21	WH01 @ 6'	0.1	Organic Content	No Odor	Yes	Lab	Soil Loads Removed					
6/9/2023 10:24	FLR01 @ 4'	0.0	No Staining	No Odor	Yes	Lab	<b>IMPACTED SOIL IDENTIFIED?</b> No					
6/9/2023 10:50	WHS01-N @ 0-6"	0.0	No Staining	No Odor	Yes	Grab	<b>ESTIMATED VOLUME OF IMPACTS:</b>					
6/9/2023 10:54	WHS01-W @ 0-6"	0.0	No Staining	No Odor	Yes	Grab	Date	Number	CY			
6/9/2023 10:58	WHS01-S @ 0-6"	0.0	No Staining	No Odor	Yes	Grab						
6/9/2023 11:00	WHS01-E @ 0-6"	0.0	No Staining	No Odor	Yes	Grab						
6/9/2023 10:34	BKG01 @ 4'	0.0	No Staining	No Odor	Yes	On-Hold						
6/9/2023 10:40	BKG01 @ 6'	0.0	No Staining	No Odor	Yes	On-Hold						
							Total Removed		0	0		
							<b>Disposal Facility:</b>					
							<b>Groundwater Recovery</b>					
							<b>DATE GW ENCOUNTERED:</b>			<b>DEPTH:</b>		
							<b>GROUNDWATER IN CONTACT WITH IMPACTED SOIL?</b>					
							<b>LNAPL OR SHEEN OBSERVED ON GW?</b>					
<b>GROUNDWATER SAMPLING</b>							Date		BBLS			
Date/Time	Groundwater Sample ID	Depth Collected	Turbid?	Sheen?	Odor?	Photo?						
							Total Removed		0			
							<b>Disposal Facility:</b>					



### Photographic Log



<b>Equipment ID:</b> FL01-07 @ 4'		<b>Equipment Type:</b>		<b>Equipment ID:</b> FL01-06 @ 4'		<b>Equipment Type:</b>	
<b>Material:</b>	<b>Volume:</b>	<b>Contents:</b>		<b>Material:</b>	<b>Volume:</b>	<b>Contents:</b>	
<b>Notes/Conditions:</b>				<b>Notes/Conditions:</b>			


Photographic Log

					
<b>Equipment ID:</b> FL01-05 @ 4'		<b>Equipment Type:</b>	<b>Equipment ID:</b> FL01-04 @ 4'		<b>Equipment Type:</b>
<b>Material:</b>	<b>Volume:</b>	<b>Contents:</b>	<b>Material:</b>	<b>Volume:</b>	<b>Contents:</b>
<b>Notes/Conditions:</b>			<b>Notes/Conditions:</b>		

Photographic Log



<b>Equipment ID:</b> FL01-03 @ 4'		<b>Equipment Type:</b>		<b>Equipment ID:</b> FL01-02 @ 4'		<b>Equipment Type:</b>	
<b>Material:</b>	<b>Volume:</b>	<b>Contents:</b>		<b>Material:</b>	<b>Volume:</b>	<b>Contents:</b>	
<b>Notes/Conditions:</b>				<b>Notes/Conditions:</b>			

					
<b>Material:</b>	<b>Volume:</b>	<b>Contents:</b>	<b>Material:</b>	<b>Volume:</b>	<b>Contents:</b>
<b>Notes/Conditions:</b>			<b>Notes/Conditions:</b>		

Photographic Log



<b>Equipment ID:</b> FLR01@4'		<b>Equipment Type:</b>		<b>Equipment ID:</b> BKG01		<b>Equipment Type:</b>	
<b>Material:</b>	<b>Volume:</b>	<b>Contents:</b>		<b>Material:</b>	<b>Volume:</b>	<b>Contents:</b>	
<b>Notes/Conditions:</b>				<b>Notes/Conditions:</b>			

Photographic Log

					
<p><b>Equipment ID:</b>WHS01-W@0-6"      <b>Equipment Type:</b></p> <p><b>Material:</b>      <b>Volume:</b>      <b>Contents:</b></p> <p><b>Notes/Conditions:</b></p>					

Photographic Log



<b>Equipment ID:</b> WHS01-S@0-6*		<b>Equipment Type:</b>		<b>Equipment ID:</b> WHS01-E@0-6*		<b>Equipment Type:</b>	
<b>Material:</b>	<b>Volume:</b>	<b>Contents:</b>		<b>Material:</b>	<b>Volume:</b>	<b>Contents:</b>	
<b>Notes/Conditions:</b>				<b>Notes/Conditions:</b>			

### Photographic Log



<b>Equipment ID:</b>		<b>Equipment Type:</b>		<b>Equipment ID:</b>		<b>Equipment Type:</b>	
<b>Material:</b>	<b>Volume:</b>	<b>Contents:</b>		<b>Material:</b>	<b>Volume:</b>	<b>Contents:</b>	
<b>Notes/Conditions:</b> CUT & CAPPED WELLHEAD				<b>Notes/Conditions:</b>			