

Operator: EXTRACTION OIL & GAS INC
Location Name: Windsor LV2 14-M Pad
Loc ID: 449441
Inspection: 697007772



Exhibit A

CA: Unused methanol rack and secondary containment, see attached photo. Comply with Rule 606.

CA Resolution: Field has reported and provided photo evidence that unused equipment has been removed to comply with Rule 606.



Exhibit A



Exhibit B



Exhibit C



Exhibit D

CA: Dead vegetation behind separators, around various locations in berms and underneath gas lines on the south side of the separators, see attached photos. Comply with Rule 606.

CA Resolution: Operator has reported and provided photo evidence that the identified debris at various locations has been cleared from to comply with Rule 606.