

Inspection Photos

Location Name: SG INTERESTS I LTD, FEDERAL-610S90W/34NWSW

Location ID: 324463

Date: 8/17/2023



SW Corner of Location – Photo #05925



SE Corner of Location – Photo #05926

Inspection Photos

Location Name: SG INTERESTS I LTD, FEDERAL-610S90W/34NWSW

Location ID: 324463

Date: 8/17/2023



NE Corner of Location – Photo #05927



Wellhead – Photo #05928

Inspection Photos

Location Name: SG INTERESTS I LTD, FEDERAL-610S90W/34NWSW

Location ID: 324463

Date: 8/17/2023



Separator – Photo #05929



Tank Battery – Photo #05930

Inspection Photos

Location Name: SG INTERESTS I LTD, FEDERAL-610S90W/34NWSW

Location ID: 324463

Date: 8/17/2023



Unprotected Soil Stockpiles at Clear Fork Crossing – Photo #05917



Unprotected Soil Stockpiles at Clear Fork Crossing – Photo #05920

Inspection Photos

Location Name: SG INTERESTS I LTD, FEDERAL-610S90W/34NWSW

Location ID: 324463

Date: 8/17/2023



Unprotected Soil Stockpiles at Clear Fork Crossing – Photo #05921



Lease Road Degradation at Clear Fork Crossing – Photo #05923