

Inspection Photos

Location Name: GUNNISON ENERGY LLC, FEDERAL-610S90W/33NWSE

Location ID: 324460

Date: 8/17/2023



Southern Entrance to Location – Photo #05936



North End of Location – Photo #05939

Inspection Photos

Location Name: GUNNISON ENERGY LLC, FEDERAL-610S90W/33NWSE

Location ID: 324460

Date: 8/17/2023



Wellhead – Photo #05937



Separator – Photo #05941

Inspection Photos

Location Name: GUNNISON ENERGY LLC, FEDERAL-610S90W/33NWSE

Location ID: 324460

Date: 8/17/2023



Tank Battery – Photo #05940



Debris Near Wellhead – Photo #05938

Inspection Photos

Location Name: GUNNISON ENERGY LLC, FEDERAL-610S90W/33NWSE

Location ID: 324460

Date: 8/17/2023



Unprotected Soil Stockpiles Near Clear Fork Crossing – Photo #05917



Unprotected Soil Stockpiles Near Clear Fork Crossing – Photo #05920

Inspection Photos

Location Name: GUNNISON ENERGY LLC, FEDERAL-610S90W/33NWSE

Location ID: 324460

Date: 8/17/2023



Unprotected Soil Stockpiles Near Clear Fork Crossing – Photo #05921



Lease Road Degradation Near Clear Fork Crossing – Photo #05923