

Inspection Photos
Location Name: CAERUS PICEANCE LLC H36X Pad
Location ID: 334926



Photo # 5995 From entrance to location



Photo # 5996 From entrance to location

Inspection Photos
Location Name: CAERUS PICEANCE LLC H36X Pad
Location ID: 334926



Photo # 6001 Location



Photo # 6002 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC H36X Pad
Location ID: 334926



Photo # 6003 Location



Photo # 6006 Debris

Inspection Photos
Location Name: CAERUS PICEANCE LLC H36X Pad
Location ID: 334926



Photo # 6008 Debris