

Inspection Photos
Location Name: CAERUS PICEANCE LLC FEDERAL 7F Pad
Location ID: 311684



Aug 18, 2023 at 9:56:52 AM
CO

Photo # 6309 From entrance to location



Aug 18, 2023 at 9:57:08 AM
CO

Photo # 6310 From entrance to location

Inspection Photos
Location Name: CAERUS PICEANCE LLC FEDERAL 7F Pad
Location ID: 311684



Photo # 6316 Location



Photo # 6317 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC FEDERAL 7F Pad
Location ID: 311684



Photo # 6318 Location



Photo # 6319 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC FEDERAL 7F Pad
Location ID: 311684




Photo # 6329 Unused equipment



Photo # 6349 Unused equipment

Inspection Photos
Location Name: CAERUS PICEANCE LLC FEDERAL 7F Pad
Location ID: 311684



Photo # 6350 Unused equipment



Photo # 6335 Debris