



99999999

L SITE INSPECTION FORM

WELL NAME Bruchie 1-25
OPERATOR Horizon O+G
LOCATION SWSW 25-33S 43W
FIELD _____

API NUMBER 05 - 009 - 5088
PERMIT NUMBER 640289
COUNTY Baca
INSPECTOR Binkley



AL/PA/DA INSPECTION RESULTS:

PASS(Y) ☒ FAIL(N) _____ DATE 4-28-89 FN _____ FD _____ WO _____

=====

DATE OF INSPECTION BEFORE/DURING DRILLING _____

CASING SIZE _____ DEPTH SET _____ CMT VOL _____ WOC _____
CONSISTENT WITH APD CASING PROGRAM? _____ RETURNS _____
RIG _____ BOP'S _____ CONTACT _____

DATE OF INSPECTION BEFORE/DURING/AFTER COMPLETION _____

PIPE SET? _____ COMPLETION RIG/ACTIVITY _____
DRILLING PITS: CLOSED _____ OPEN _____ WELLHEAD SYSTEM INSTALLED _____
TANK ID: YES _____ NO _____ NA _____ WELL SIGN: YES _____ NO _____
SKIM PIT: _____ gal TANKS: () _____ bbls
EQUIPMENT _____

BRADENHEAD PRESSURE _____ FLUID: NO _____ YES _____ TYPE _____
METER RUN: YES _____ NO _____ WELL STATUS: PR _____ TA _____ SI _____ WELL CAT 3- _____

AL/PA/DA INSPECTION

DATE PLUGGED: 4-5-8-68 DATE PERMIT EXPIRED: _____
HOLE PLUGGED: YES ☒ NO _____ PITS BACKFILLED: YES ☒ NO _____
MATERIAL BURIED: YES ☒ NO _____ NA _____ SITE CLEAN: YES ☒ NO _____
BOND RELEASE OK: YES ☒ NO _____ FED _____ HOLE MARKER: YES _____ NO ☒

DATE OF SAFETY/STATUS INSPECTION _____

COMMENTS Cultivated



00640094