

# Final Reclamation Inspection

August 15, 2023

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 332915

Inspection Document #: 697504794

Weld County, CO

NWSE Section 13 T2N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: HEIT-62N67W 13NWSE  
Location ID: 332915



**Photo 1.** Photo taken from the approximate well locations, facing North. Photo illustrates the well location appears reflective of reference area vegetation.



**Photo 2.** Photo taken from the approximate well locations, facing West. See comments under Photo 1.

Note- the access road is in use for an active tank battery that was not associated with these well locations.



# Inspection Photos

Location Name: HEIT-62N67W 13NWSE

Location ID: 332915



**Photo 3.** Photo taken from the approximate well locations, facing South. See comments under Photo 1.



**Photo 4.** Photo taken from the approximate wellhead, facing East. See comments under Photo 1.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Number: 697504794





**Photo 5.** Photo taken from the approximate associated offsite tank battery, facing South. Photo illustrates the tank battery is stabilized and appears to be in use for residential development.