

Location:	Champlin Danford #1
Line:	Well to Separator
Technicians:	Cody Baylis
Date	9/24/2019
Time	Pressure (PSI)
4:55:10 PM	4.7
4:55:40 PM	4.9
4:56:10 PM	4.8
4:56:40 PM	4.8
4:57:10 PM	97.6
4:57:40 PM	97.5
4:58:10 PM	97.5
4:58:40 PM	97.4
4:59:10 PM	97.3
4:59:40 PM	97.3
5:00:10 PM	97.3
5:00:40 PM	97.2
5:01:10 PM	97.1
5:01:40 PM	97.1
5:02:10 PM	97.1
5:02:40 PM	97.1
5:03:10 PM	97
5:03:40 PM	97
5:04:10 PM	96.9
5:04:40 PM	96.9
5:05:10 PM	96.8
5:05:40 PM	96.8
5:06:10 PM	96.8
5:06:40 PM	96.7
5:07:10 PM	96.7
5:07:40 PM	96.7
5:08:10 PM	96.7
5:08:40 PM	96.7
5:09:10 PM	96.7
5:09:40 PM	96.7
5:10:10 PM	96.7
5:10:40 PM	96.7
5:11:10 PM	96.6
5:11:40 PM	96.6
5:12:10 PM	96.6
5:12:40 PM	96.6
5:13:10 PM	96.6
5:13:40 PM	96.6
5:14:10 PM	96.6
5:14:40 PM	96.6
5:15:10 PM	96.6
5:15:40 PM	96.6

5:16:10 PM	96.5
5:16:40 PM	96.5
5:17:10 PM	96.5
5:17:40 PM	96.5
5:18:10 PM	96.5
5:18:40 PM	96.5
5:19:10 PM	96.4
5:19:40 PM	96.4
5:20:10 PM	96.4
5:20:40 PM	96.4
5:21:10 PM	96.4
5:21:40 PM	96.4
5:22:10 PM	96.4
5:22:40 PM	96.4
5:23:10 PM	96.4
5:23:40 PM	96.4
5:24:10 PM	96.4
5:24:40 PM	96.4
5:25:10 PM	96.4
5:25:40 PM	96.4
5:26:10 PM	96.4
5:26:40 PM	96.4
5:27:10 PM	96.4
5:27:40 PM	96.4
5:28:10 PM	96.4
5:28:40 PM	96.4
5:29:10 PM	96.4
5:29:40 PM	2.9
5:30:10 PM	3.9
5:30:40 PM	4.1
5:31:10 PM	4.6
5:31:40 PM	5
5:32:10 PM	5.3

Pass/Fail

% loss over 30 minutes	1.23%	Less than 10%	Yes		
% loss in last 5 minutes	0.00%	Less than 1%	Yes		Pass

