



LORADO OIL & GAS CONSERVATION COMMISSION
FIELD INSPECTION REPORT

MAY 13 1996



☒ NOTICE OF UNSATISFACTORY INSPECTION

☐ NOTICE OF SATISFACTORY INSPECTION

1120 Lincoln Street, Suite 801
Denver, CO 80203
(303)894-2100

API No. 05- 009 - 6130

LEASE NAME: EDITH M. LEWIS #1

LOCATION: NESW 33-34S41W

OPERATOR: KODIAK DRILLING

DATE: 4-8-96

INSPECTOR: R. VanSickle

Insp. Type: ID

Insp. Status: SI

PA: Y

N

Pass/Fail: P

F

Viol.: Y

N

NOV: Y

N

INSPECTION ITEM

COMMENTS

INPUT

Well ID Signs

(Rule 210)

No phone numbers, no location.

Pits (Reserve/Production)

(Rule 902, 903, 904)

None.

Fences

(Rule 604.C.(3), 1003.A)

None.

Tank Battery Equipment

(Rule 604)

Leak, GMR, 3 150 BBL into the

Fire Walls/Berms/Dikes

(Rule 604)

None.

General Housekeeping

(Rule 603.G)

OK.

Spills (Oil/Water)

(Rule 908)

None.

Bradenhead

(Rule 207)

—

Drilling Well/Workover

(Rule 315)

—

Surface Rehabilitation

(Rule 317)

—

Miscellaneous

Water run blinded 8-30-93.

CORRECTIVE ACTION REQUIRED: MIT, Produce or plug. Install berms and update sign if kept.

Date Corrective Action Required By: 10-8-96.

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.