

Storm Water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 7D Pad
Location ID: 334073



**Location Overview: Location is within Black Bear/High
Priority/NSO Habitat areas. Location is approximately 91
yards from Pete & Bill Creek.**

Section/Township/Range: 7 8S95W

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 7D Pad
Location ID: 334073



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.



Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 7D Pad
Location ID: 334073



Photo # 6266 Lack of stabilization/compaction



Photo # 6267 Lack of stabilization/compaction

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 7D Pad
Location ID: 334073



Photo # 6268 Lack of stabilization/compaction



Photo # 6269 Lack of stabilization/compaction

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 7D Pad
Location ID: 334073



Photo # 6281 Lack of stabilization/compaction



Photo # 6282 Lack of stabilization/compaction

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 7D Pad
Location ID: 334073



Photo # 6283 Lack of stabilization/compaction



Photo # 6287 Lack of stabilization/compaction

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 7D Pad
Location ID: 334073



Photo # 6297 Ditch needs maintenance/transport of sediment onto lease road (on lease road across from spur road turnoff to location)



Photo # 6298 Ditch needs maintenance/transport of sediment onto lease road (on lease road across from spur road turnoff to location)

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 7D Pad
Location ID: 334073



Photo # 6300 BMP's laying on slope in multiple areas along lease road