

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 7D Pad

Location ID: 334073



Photo # 6229 From entrance to location



Photo # 6230 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC FEDERAL 7D Pad
Location ID: 334073



Photo # 6232 Location



Photo # 6246 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 7D Pad

Location ID: 334073



Photo # 6235 Location

Photo # 6236 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC FEDERAL 7D Pad
Location ID: 334073



Photo # 6237 Unmarked deadman



Photo # 6238 Same unmarked deadman from a different angle

Inspection Photos
Location Name: CAERUS PICEANCE LLC FEDERAL 7D Pad
Location ID: 334073



Photo # 6239 Debris



Photo # 6240 Debris

Inspection Photos
Location Name: CAERUS PICEANCE LLC FEDERAL 7D Pad
Location ID: 334073



Photo # 6241 Debris



Photo # 6242 Debris

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 7D Pad

Location ID: 334073



Photo # 6243 Debris



Photo # 6244 Stained soils & gravel

Inspection Photos
Location Name: CAERUS PICEANCE LLC FEDERAL 7D Pad
Location ID: 334073



Photo # 6251 Debris



Photo # 6253 Debris

