



99999999

## WELL SITE INSPECTION FORM



WELL NAME Griffin 1  
OPERATOR Horizon  
LOCATION SWSW 15-33S-43W  
FIELD \_\_\_\_\_

( API NUMBER 05 - 009 - 5102 )  
PERMIT NUMBER \_\_\_\_\_  
COUNTY Baca  
INSPECTOR Binkley

## AL/PA/DA INSPECTION RESULTS:

PASS(Y) ☒ FAIL(N) \_\_\_\_\_ DATE 9-14-88

## WELL STATUS:

FN \_\_\_\_\_ FD \_\_\_\_\_ WO \_\_\_\_\_

=====

DATE OF INSPECTION BEFORE/DURING DRILLING \_\_\_\_\_

CASING SIZE \_\_\_\_\_ DEPTH SET \_\_\_\_\_ CMT VOL \_\_\_\_\_ WOC \_\_\_\_\_  
CONSISTENT WITH APD CASING PROGRAM? \_\_\_\_\_ RETURNS \_\_\_\_\_  
RIG \_\_\_\_\_ BOP'S \_\_\_\_\_ CONTACT \_\_\_\_\_

DATE OF INSPECTION BEFORE/DURING/AFTER COMPLETION \_\_\_\_\_

PIPE SET? \_\_\_\_\_ COMPLETION RIG/ACTIVITY \_\_\_\_\_

DRILLING PITS: CLOSED \_\_\_\_\_ OPEN \_\_\_\_\_ WELLHEAD SYSTEM INSTALLED \_\_\_\_\_

TANK ID: YES \_\_\_\_\_ NO \_\_\_\_\_ NA \_\_\_\_\_ WELL SIGN: YES \_\_\_\_\_ NO \_\_\_\_\_

SKIM PIT: \_\_\_\_\_ gal TANKS: ( ) \_\_\_\_\_ bbls

EQUIPMENT \_\_\_\_\_

BRADENHEAD PRESSURE \_\_\_\_\_ FLUID: NO \_\_\_\_\_ YES \_\_\_\_\_ TYPE \_\_\_\_\_

METER RUN: YES \_\_\_\_\_ NO \_\_\_\_\_ WELL STATUS: PR \_\_\_\_\_ TA \_\_\_\_\_ SI \_\_\_\_\_ WELL CAT 3- \_\_\_\_\_

## AL/PA/DA INSPECTION

DATE PLUGGED: 12-21-82

DATE PERMIT EXPIRED: \_\_\_\_\_

HOLE PLUGGED: YES ☒ NO \_\_\_\_\_

PITS BACKFILLED: YES ☒ NO \_\_\_\_\_

MATERIAL BURIED: YES ☒ NO \_\_\_\_\_ NA \_\_\_\_\_

SITE CLEAN: YES ☒ NO \_\_\_\_\_

BOND RELEASE OK: YES ☒ NO \_\_\_\_\_ FED \_\_\_\_\_

HOLE MARKER: YES \_\_\_\_\_ NO ☒

DATE OF SAFETY/STATUS INSPECTION \_\_\_\_\_

COMMENTS grassland



00640343

3/1/79

NGPA  
Filing Fee

Date Check Received

Oct. 29, 1979

FILING NO(S). 79-488

And/Or

WELL NAME(S) Griffin #1-15

Date of Check 10/24/79

Check # 1687 Amt. \$ 700.<sup>00</sup>

Name of Company Bruce Calder, Inc.

Maker of Check Sane

Bank Check Issued On Republic Nat'l Bank  
(Dallas, Tx)