

Inspection Photos
Location Name: Windsor LV 214-M Pad
Location ID: 449441



Lease road entrance



Production facility

Inspection Photos
Location Name: Windsor LV 214-M Pad
Location ID: 449441



Unused equipment on 7/27/2023



Unused equipment on 8/22/2023

Inspection Photos
Location Name: Windsor LV 214-M Pad
Location ID: 449441



Debris under gas lines on 7/27/2023



Debris under gas lines on 8/22/2023

Inspection Photos
Location Name: Windsor LV 214-M Pad
Location ID: 449441



Energy & Carbon Management Commission
40.4813, -104.85234, 1446.3m, 185°
08/22/2023 11:37:19

Debris on 8/22/2023



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources