

Inspection Photos
Location Name: Gordon-63N61W 5NWSE Tank Battery
Location ID: 326779



August 21, 2023 at 8:39 AM
+40.2524, -104.2325
294° NW
Weld County
Energy & Carbon Management Commission

Location Sign



August 21, 2023 at 8:33 AM
+40.2524, -104.2326
159° S
Weld County
Energy & Carbon Management Commission

Tank Battery



Inspection Photos
Location Name: Gordon-63N61W 5NWSE Tank Battery
Location ID: 326779



Overgrown Vegetation and Weathered Berms



Overgrown Vegetation and Weathered Berms

Inspection Photos
Location Name: Gordon-63N61W 5NWSE Tank Battery
Location ID: 326779



Overgrown Vegetation and Weathered Berms



Overgrown Vegetation and Weathered Berms

Inspection Photos
Location Name: Gordon-63N61W 5NWSE Tank Battery
Location ID: 326779



Overgrown Vegetation and Weathered Berms



Overgrown Vegetation and Weathered Berms

Inspection Photos
Location Name: Gordon-63N61W 5NWSE Tank Battery
Location ID: 326779



Unused Meter shed door



Production Equipment

Inspection Photos
Location Name: Gordon-63N61W 5NWSE Tank Battery
Location ID: 326779



Overgrown Vegetation



Overgrown Vegetation