

## Inspection Photos

Location Name: "F" Quarter Circle-63N61W 8NWSW Tank Battery

Location ID: 327148



**Overgrown Vegetation**

**Unused Water Tank**

## Inspection Photos

Location Name: "F" Quarter Circle-63N61W 8NWSW Tank Battery

Location ID: 327148



**Unused Water Tank**



**Stained Soil**

# Inspection Photos

Location Name: "F" Quarter Circle-63N61W 8NWSW Tank Battery

Location ID: 327148



August 21, 2023 at 9:36 AM  
+40.2380, -104.2419  
142° SE  
Weld County  
Energy & Carbon Management Commission



August 21, 2023 at 9:36 AM  
+40.2380, -104.2419  
105° E  
Weld County  
Energy & Carbon Management Commission

**Overgrown Vegetation**

**Overgrown Vegetation**

# Inspection Photos

Location Name: "F" Quarter Circle-63N61W 8NWSW Tank Battery

Location ID: 327148



**Overgrown Vegetation**

**Overgrown Vegetation**

## Inspection Photos

Location Name: "F" Quarter Circle-63N61W 8NWSW Tank

Location ID: 327148



August 21, 2023 at 9:34 AM

+40.2379, -104.2416

177° S

Weld County

Energy & Carbon Management Commission

**Overgrown Vegetation**

