

Inspection Photos

Location Name: HSR-Hobe State-63N62W 32NWN Tank Battery

Location ID: 330074



Sign



Removed Overgrown vegetation in tank battery



Inspection Photos

Location Name: HSR-Hobe State-63N62W 32NWE Tank Battery

Location ID: 330074



Overgrown Vegetation



Overgrown Vegetation

Inspection Photos

Location Name: HSR-Hobe State-63N62W 32NWE Tank Battery

Location ID: 330074



Overgrown Vegetation



Overgrown Vegetation