



LORADO OIL & GAS CONSERVATION COMMISSION
FIELD INSPECTION FORM

C

<input checked="" type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100	
<input type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION			
API No. 05- 009 - 06024		LEASE NAME: MAYBERRY #1	
LOCATION: NENW10-34S-41W		OPERATOR: MIDWEST EXPL.	
DATE: 5-2-95		INSPECTOR: R. VanSickle	
Insp. Type: PR	Insp. Status: PR	PA: Y N	Pass/Fail: P F Viol.: Y N NOV: Y N

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs	NONE.	✓
Pits (Reserve/Production)	NONE.	
Fences	AROUND BTRY.	
Tank Battery Equipment	3 300 [±] , FWKO, vent., heater treater, water tank, pump unit.	✓
Fire Walls/Berms/Dikes	None.	
General Housekeeping	Only soil in ridge on west side of btry site. Some oil @ wellhead.	✓
Spills (Oil/Water)	✓	
Bradenhead	—	
Drilling Well/Workover	—	
Surface Rehabilitation	—	
Miscellaneous	—	

CORRECTIVE ACTION REQUIRED: Install sign per Rule 210. Clean up & dispose of oily dirt.

Date Corrective Action Required By: 7-15-95 **Date Remedied:**

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.