



00632132

BEST IMAGE  
AVAILABLE

## LEASE INSPECTION FORM

Date 6/6/85  
Operator Amoco Field GREENWOOD  
Lease Name & No. MAYBERLY #1 County BALA  
Tank Battery No. 34341610 Location NENW 10-34S-41W  
Legal Description  
Type of Inspection GENERAL / P17  
Water Inflow 0 (Bbls. Per Day)

## RESULTS OF INSPECTION

(Est. Pit Dimensions, CVD, Lined, Oil on Surface, etc.)  
Type of Tank

SKIM TANK \_\_\_\_\_

Pit No. 1 20'x30' FENCED - 100% OIL BROWDER PIT / VENT LINE  
NOTE: WATER DISPOSED IN MAYBERLY #25WD Basin

Pit No. 2 \_\_\_\_\_

Pit No. 3 \_\_\_\_\_

ADDITIONAL PITS \_\_\_\_\_

CONDITION OF LEASE (Describe - Oil CVD. or Sat. Gr., Any Leaking, Safety  
Conditions, Etc.)

LEASE SIGN NEEDS LEGALS BTC TK NOS. OKTKS FENCED, PUMPS FENCED. LGE AREA OF OIL SAT. GROUNDNW & TK BOTTOMS -RECOMMENDED ACTION (If Required) DRAIN OR COVER PIT, FIX LEASE SIGNINSPECTOR ROBERT L. VALLANK