

Inspection Photos
Location Name: CAERUS PICEANCE LLC FEDERAL 8C Pad
Location ID: 334081



Photo # 6451 From entrance to location



Photo # 6452 From entrance to location

Inspection Photos
Location Name: CAERUS PICEANCE LLC FEDERAL 8C Pad
Location ID: 334081



Photo # 6453 From entrance to location



Photo # 6457 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC FEDERAL 8C Pad
Location ID: 334081



Photo # 6458 Location



Photo # 6459 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC FEDERAL 8C Pad
Location ID: 334081



Photo # 6461 Location



Photo # 6479 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 8C Pad

Location ID: 334081



Photo # 6480 Location



Photo # 6460 Wildlife/personnel hazard

Inspection Photos
Location Name: CAERUS PICEANCE LLC FEDERAL 8C Pad
Location ID: 334081



Photo # 6468 Debris & staining



Photo # 6469 Debris

Inspection Photos
Location Name: CAERUS PICEANCE LLC FEDERAL 8C Pad
Location ID: 334081



Photo # 6470 Debris & staining



Photo # 6244 Staining

Inspection Photos
Location Name: CAERUS PICEANCE LLC FEDERAL 8C Pad
Location ID: 334081



Photo # 6475 Tank/label missing required information



Photo # 6476 Tank/label missing required information

Inspection Photos
Location Name: CAERUS PICEANCE LLC FEDERAL 8C Pad
Location ID: 334081



Photo # 6481 Unused equipment




Photo # 6482 Unused equipment

Inspection Photos
Location Name: CAERUS PICEANCE LLC FEDERAL 8C Pad
Location ID: 334081



Photo # 6488 Debris



Photo # 6491 Debris

Inspection Photos
Location Name: CAERUS PICEANCE LLC FEDERAL 8C Pad
Location ID: 334081




Photo # 6519 Debris



Photo # 6536 Debris

Inspection Photos
Location Name: CAERUS PICEANCE LLC FEDERAL 8C Pad
Location ID: 334081



Photo # 6537 Debris



Photo # 6538 Debris

Inspection Photos
Location Name: CAERUS PICEANCE LLC FEDERAL 8C Pad
Location ID: 334081



Photo # 6491 Stained soils & gravel



Photo # 6494 Stained soils & gravel

Inspection Photos
Location Name: CAERUS PICEANCE LLC FEDERAL 8C Pad
Location ID: 334081



Photo # 6496 Stained soils & gravel



Photo # 6521 Liner needs maintenance

Inspection Photos
Location Name: CAERUS PICEANCE LLC FEDERAL 8C Pad
Location ID: 334081



Photo # 6522 Liner needs maintenance



Photo # 6523 Liner needs maintenance