

Inspection Photos

8/21/2023

Operator: CAERUS PICEANCE LLC #10456

Location Number: 479215

Rio Blanco County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location Number: 479215



Photo 1: Signage remains missing at Location entrance.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location Number: 479215



August 21, 2023



August 21, 2023

Photo 2: Photo taken from the south end of the Location; excavation has been backfilled. Photo shows topsoil protections remained inadequate; Operator has mixed topsoil with subsoils.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 479215



Photo 3: Photo shows BMPs to minimize erosion, degradation, sediment transport, as well as to protect topsoil remain missing or insufficient at stockpile on the south end of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 479215



Photo 4: Sediment trap and culvert on the south end of the Location not installed. Ditch on SE end not installed.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 479215



Photo 5: Sediment traps on Location remain unchanged; BMPs inadequate in size; outlets/spillways not installed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 479215



Photo 6: Photos examples showing erosion logs remain in improper functioning condition; BMPs either compressed, or not properly trenched/backfilled.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location Number: 479215



Photo 7: Photos examples showing hydromulch at the topsoil stockpiles is in disrepair.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 479215



Photo 8: Controls to minimize erosion/degradation remain missing or insufficient along sections of the cut slopes.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location Number: 479215



Photo 9: Slope drains along perimeter of the WPS not implemented per SWMP.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location Number: 479215



Photo 10: Porta-johns secured.