

WELL SITE INSPECTION FORM
(DRILLING AND PLUGGING)



99999999

Well Name MAYBERRY # 1-9 API Number 05 - 009 - 6049
Operator TRIGG Permit # 71 934
Location NE NE 9 34S 41W County BOCA
Field _____ Inspector SUELTON

AL/PA/DA Inspection Results:

Well Status:

Pass(Y) _____ Fail(N) N Date 2/25/93 ND _____ DG _____ WO _____ PR _____ SI _____ TA _____

Date of Inspection Before/During Drilling _____

Surf. Csg. Size _____ Setting Depth _____ Cmt. Vol. _____ WOC time _____
Consistent with APD casing Program? YES _____ NO _____ Returns _____
Rig _____ BOP'S _____ Stage Tool Depth _____ Cmt. Vol. _____

Date of Inspection Before/During/After Completion _____

Prod. Csg. Set? _____ Completion Rig/Activity _____
Drilling Pits: Closed _____ Open _____ Wellhead Installed: _____ Sign: Yes _____ No _____
Tank ID: Yes _____ No _____ N/A _____ Skim Tank/Pit: _____ Prod. Tanks: () _____ BBLs
Equipment _____ Meter Run: Yes _____ No _____
Bradenhead Press: _____ Fluid: No _____ Yes _____ Type _____ Well Cat. _____

AL/PA/DA Inspection

Date Plugged: _____ Date Permit Expired: _____
Hole Plugged: Yes X No _____ Pits Backfilled: Yes _____ No X
Material Buried: Yes _____ No _____ N/A X Site Clean: Yes _____ No X
Bond Release OK: Yes _____ No X Fed _____ Hole Marker: Yes _____ No X

Date of Safety/Status Inspection 2/25/93

Comments: OLD DA / PITS OPEN, OVERGROWN, STILL FENCED /
GRASSLAND / NSSC - FOUND 2' CUT OFF STUB IN CIRC PIT
/ NOT A PROBLEM



00632039

Violations: Yes _____ No _____ Notice Sent: Yes _____ No _____ Date Sent: _____