

**Storm Water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC WALLING Pad**  
**Location ID: 334062**



**Location Overview: Location is within High  
Priority/Density/Black Bear Habitat areas.**

**Section/Township/Range: 1 8S96W**

**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC WALLING Pad**  
**Location ID: 334062**



**North West corner of location.**



**North East corner of location.**



**South West corner of location.**



**South East corner of location.**

**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC WALLING Pad**  
**Location ID: 334062**



**Photo # 6937 Improperly stored chemicals/chemical containers**



**Photo # 6942 Erosion of berm & transport of sediment off location & into a vegetated area**

**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC WALLING Pad**  
**Location ID: 334062**



**Photo # 6942 Erosion of berm & transport of sediment off location & into a vegetated area**



**Photo # 6944 Erosion of berm & transport of sediment off location & into a vegetated area**

**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC WALLING Pad**  
**Location ID: 334062**



**Photo # 6945 Erosion of berm & transport of sediment off location & into a vegetated area**



**Photo # 6946 Erosion of berm & transport of sediment off location & into a vegetated area**

**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC WALLING Pad**  
**Location ID: 334062**



**Photo # 6947 Erosion of berm & transport of sediment off location & into a vegetated area**



**Photo # 6948 Erosion of berm & transport of sediment off location & into a vegetated area**

**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC WALLING Pad**  
**Location ID: 334062**



**Photo # 6949 Erosion of berm & transport of sediment off location & into a vegetated area**