



00695731

WELL SITE INSPECTIONOPERATOR Kimback O&GDATE 6/18/86WELL NAME #1 Commerce RanchCOUNTY Baca

RIG _____

LEGAL E/R MW S 22 T 33 R 44

SURFACE CASING _____ SIZE _____ DEPTH _____ DATE _____

CEMENT VOLUME _____ RETURNS _____ WOC _____

PROBABLE FOX HILLS DEPTH _____

MUD PITS _____

DISPOSAL _____

PRODUCTION STRING _____ SIZE _____ DEPTH _____

STAGED _____ CBL CHECKED _____

SQUEEZE _____ FRAC JOB _____

BATTERY _____ SIGN _____

SITE INSPECTION AFTER DRILLING Excellent REHAB. LOCATION 100%LEVELLED & overgrown - very green. NO JUNK

DIRECTIONS _____

ACTION OK TO RELEASE FROM BONDENGINEER R. VACLAVIK