



Description:

#1 - Phelps Facility



Description:

#2 - Looking North into Doghouse where Sight Glass Failed. Note Presence of Groundwater in Floor of Excavation.

Photo Log



Description:

#3 - Looking East at Separator. Groundwater is present in Excavation. Hand augered boring has delineated extent of impacts.

Photo Log



Description:

#4 - Depth to Groundwater is Approximately 2.5 Feet. Free phase oil was present on Groundwater.