

**Operator: EXTRACTION OIL & GAS INC**  
**Location Name: Windsor LV2 14-M Pad**  
**Loc ID: 449441**  
**Inspection: 697007930**



**Exhibit A**

**CA:** Debris noted in prior FIR #697007772 has been removed from below gas lines and placed on south side of location, see attached photos. Remove debris per Rule 606.

**CA Resolution:** Field has reported and provided photo evidence that the identified debris has been addressed and cleared from the location to comply with Rule 606.