

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403510240

Date Received:
08/25/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10679

Name of Operator: LOGOS OPERATING LLC

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87401

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
Dacye Shull	505-787-2027	dshull@logosresourcesllc.com
Vanessa Fields	505-787-2218	vfields@logosresourcesllc.com
Etta Trujillo	505-324-4145	etrujillo@logosresourcecellc.com

OGCC INSPECTION SUMMARY:

FIR Document Number: 712700552

Inspection Date: 08/21/2023

FIR Submit Date: 08/21/2023

FIR Status: _____

Inspected Operator Information:

Company Name: LOGOS OPERATING LLC

Company Number: 10679

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87401

LOCATION - Location ID: 306978

Location Name: OLGUIN-N32N6W Number: 18NWNW County: LA PLATA

Qtrqtr: NWN Sec: 18 Twp: 32N Range: 6W Meridian: N

Latitude: 37.021710 Longitude: -107.547180

FACILITY - API Number: 05-067-00 Facility ID: 288965

Facility Name: OLGUIN Number: 1A

Qtrqtr: NWN Sec: 18 Twp: 32N Range: 6W Meridian: N

Latitude: 37.021710 Longitude: -107.547180

CORRECTIVE ACTIONS:

1 CA# 179135

Corrective Action: Install proper guy line markers per Rule 1003.a

Date: 09/04/2023

Response: CA COMPLETED

Date of Completion: 08/24/2023

Guy anchor repaired.

--

Print Name: Deane Shull Signed:

Signed:

Date: 8/25/2023 2:54:04 PM

□ □ □ 1 2 3 4 5