

Operator: EXTRACTION OIL & GAS INC

Location Name: Lind 26-D

Loc ID: 458152

Inspection: 697007736



Exhibit A

CA: Sign not posted at battery. Install sign to comply with Rule 605.e.

CA Resolution: Field has reported and provided photo evidence that signage has been appropriately installed at the battery to comply with Rule 605.e.



Exhibit A



Exhibit B

CA: Miscellaneous equipment around location; see attached photos. Comply with Rule 606.

CA Resolution: Field has reported and provided photo evidence that the identified unused equipment has been removed from the location to comply with Rule 606.



Exhibit A

CA: Bulk lube oil storage tank lacks wildlife protection, see attached photo. Install or repair wildlife protection equipment.

CA Resolution: Field has reported and provided photo evidence to show that netting for wildlife protection has been appropriately installed on the bulk lube oil storage tank to comply with Rule 902.b.