

# State of Colorado Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403452166

Receive Date:

07/03/2023

Report taken by:

Kari Brown

## Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by COGCC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Closure request is not available for an Initial Site Investigation and Remediation Workplan.

### OPERATOR INFORMATION

Name of Operator: <u>CRESTONE PEAK RESOURCES OPERATING LLC</u>	Operator No: <u>10633</u>	<b>Phone Numbers</b>
Address: <u>1801 CALIFORNIA STREET #2500</u>		Phone: <u>(303) 2947864</u>
City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>		Mobile: <u>(303) 8293811</u>
Contact Person: <u>Jacob Evans</u>	Email: <u>jevans@civiresources.com</u>	

### PROJECT, PURPOSE & SITE INFORMATION

#### PROJECT INFORMATION

Remediation Project #: 21354 Initial Form 27 Document #: 402890783

#### PURPOSE INFORMATION

- ☐ Rule 913.c.(1): Pit or Cuttings Trench closure.
- ☐ Rule 913.c.(2): Buried or partially buried vessel closure, which will be by removal.
- ☒ Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912.
- ☐ Rule 913.c.(4): Land treatment of Oily Waste pursuant to Rule 905.e.
- ☐ Rule 913.c.(5): Closure of Centralized E&P Waste Management Facilities pursuant to Rule 907.h.
- ☒ Rule 913.c.(6): Remediation of impacted Groundwater pursuant to Rule 915.e.(3).D, and the contaminant concentrations in Table 915-1.
- ☐ Rule 913.c.(7): Investigation and remediation of natural gas in soil or Groundwater.
- ☐ Rule 913.c.(8): When requested by the Director due to any potential risk to soil, Groundwater, or surface water.
- ☐ Rule 913.c.(9): Decommissioning of Oil and Gas Facilities.
- ☐ Rule 913.g: Changes of Operator.
- ☐ Rule 915.b: Request to leave elevated inorganics in situ.
- ☐ Other: \_\_\_\_\_

#### SITE INFORMATION

☐ Yes ☐ Multiple Facilities

Facility Type: <u>LOCATION</u>	Facility ID: <u>321484</u>	API #: _____	County Name: <u>BOULDER</u>
Facility Name: <u>HARSCH-62N69W 27NWNE</u>	Latitude: <u>40.114530</u>	Longitude: <u>-105.100390</u>	
** correct Lat/Long if needed: Latitude: <u>40.112761</u>		Longitude: <u>-105.101428</u>	
QtrQtr: <u>NWNE</u> Sec: <u>27</u> Twp: <u>2N</u> Range: <u>69W</u> Meridian: <u>6</u>	Sensitive Area? <u>Yes</u>		
Facility Type: <u>SPILL OR RELEASE</u>	Facility ID: <u>480825</u>	API #: _____	County Name: <u>BOULDER</u>
Facility Name: <u>Harsch 42-27</u>	Latitude: <u>40.106048</u>	Longitude: <u>-105.096846</u>	
** correct Lat/Long if needed: Latitude: <u>40.112761</u>		Longitude: <u>-105.101428</u>	
QtrQtr: <u>SESE</u> Sec: <u>27</u> Twp: <u>2N</u> Range: <u>69W</u> Meridian: <u>6</u>	Sensitive Area? <u>Yes</u>		

## **SITE CONDITIONS**

General soil type - USCS Classifications SM

Most Sensitive Adjacent Land Use Cropland

Is domestic water well within 1/4 mile? Yes

Is surface water within 1/4 mile? Yes

Is groundwater less than 20 feet below ground surface? Yes

### **Other Potential Receptors within 1/4 mile**

Irrigation canal, occupied structures, and residential area

## SITE INVESTIGATION PLAN

### TYPE OF WASTE:

- ☒ E&P Waste ☐ Other E&P Waste ☐ Non-E&P Waste
- ☒ Produced Water ☐ Workover Fluids
- ☒ Oil ☐ Tank Bottoms
- ☒ Condensate ☐ Pigging Waste
- ☐ Drilling Fluids ☐ Rig Wash
- ☐ Drill Cuttings ☐ Spent Filters
- ☐ Pit Bottoms
- ☐ Other (as described by EPA)

### DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
Yes	GROUNDWATER	To be determined	Investigation pending
Yes	SOILS	To be determined	Investigation pending

### INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

On September 14, 2021, a flowline between the well and separator failed a pressure test at the Harsch 42-27 Battery (Location ID: 321484), indicating a potential release of an unknown volume of production fluids. Form 19 Initial (document number 402811540) was submitted to notify the COGCC of the reportable release; however, due to miscommunication, the report incorrectly cited Location ID 321319 as the spill location instead of the correct Location ID 321484. A correction will be submitted in the Form 19 supplemental to close out the Spill/Release Point ID 480825. The location passed a pressure test in May 2020 and has been shut in since June 2021. Initial site investigation was conducted October 8, 2021 to characterize potential impacts associated with the release. Four characterization potholes (SB01-SB04) were advanced along the failed flowline path within the boundaries of the working surface. One background pothole (BKG01) was advanced outside of the working surface. Soil samples were collected from just beneath the depth of the buried line to characterize potential soil impacts. Groundwater was encountered during site investigation at approximately 4 feet below ground surface (bgs), and a groundwater sample was collected from the pothole location demonstrating the greatest degree of groundwater hydrocarbon sheen to characterize potential dissolved phase impacts. A background groundwater sample was also collected from BKG01. Soil and groundwater samples were submitted for analysis of Table 915-1 organic and inorganic constituents of concern. Characterization soil samples exceeded Table 915-1 allowable limits for soil suitability for reclamation constituents and metals. The characterization groundwater sample (SB01\_GW) exceeded Table 915-1 allowable limits for benzene. See Figure 2 for sample locations and Tables 1 and 2 for analytical data.

### PROPOSED SAMPLING PLAN

#### Proposed Soil Sampling

☒ Will soil samples be collected as part of this investigation? ( Number, type (grab/composite), analyses, and locations of samples ):

Five grab soil samples were collected for analysis of Table 915-1 TPH C6-36, organics, metals, EC, SAR, pH, and boron.

#### Proposed Groundwater Sampling

☒ Will groundwater samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

One grab groundwater sample was collected for analysis of BTEX, naphthalene, 1,2,4-trimethylbenzene, 1,3,5-trimethylbenzene, TDS, chlorides, and sulfates.

#### Proposed Surface Water Sampling

☐ Will surface water samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

### Additional Investigative Actions

☐ Additional alternative investigative actions described in attached Site Investigation Plan ( summary ):

## SITE INVESTIGATION REPORT

## SAMPLE SUMMARY

### Soil

Number of soil samples collected 6  
Number of soil samples exceeding 915-1 6  
Was the areal and vertical extent of soil contamination delineated? No  
Approximate areal extent (square feet) 5000

### NA / ND

ND Highest concentration of TPH (mg/kg) \_\_\_\_\_  
-- Highest concentration of SAR 13.8  
BTEX > 915-1 No  
Vertical Extent > 915-1 (in feet) 6

### Groundwater

Number of groundwater samples collected 2  
Was extent of groundwater contaminated delineated? No  
Depth to groundwater (below ground surface, in feet) 4  
Number of groundwater monitoring wells installed 0  
Number of groundwater samples exceeding 915-1 2

-- Highest concentration of Benzene (µg/l) 88  
-- Highest concentration of Toluene (µg/l) 27  
-- Highest concentration of Ethylbenzene (µg/l) 2.1  
-- Highest concentration of Xylene (µg/l) 42  
NA Highest concentration of Methane (mg/l) \_\_\_\_\_

### Surface Water

0 Number of surface water samples collected  
0 Number of surface water samples exceeding 915-1  
If surface water is impacted, other agency notification may be required.

## OTHER INVESTIGATION INFORMATION

☐ Were impacts to adjacent property or offsite impacts identified?

☒ Were background samples collected as part of this site investigation?

Background samples were collected from the boreholes outside of the source area for analysis of Table 915-1 metals, SAR, EC, pH, and boron.

☐ Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards) \_\_\_\_\_ Volume of liquid waste (barrels) \_\_\_\_\_

☐ Is further site investigation required?

## REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No

## SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

No soil impacts were discovered during site assessment activities.

## REMEDIATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

Five monitoring wells were installed to monitor natural attenuation. The anticipated timeframe to achieve a no further action will be November 30, 2023.

## Soil Remediation Summary

☐ In Situ

☐ Ex Situ

\_\_\_\_\_  
Bioremediation ( or enhanced bioremediation )

\_\_\_\_\_  
Excavate and offsite disposal

☐ Chemical oxidation  
☐ Air sparge / Soil vapor extraction  
☐ Natural Attenuation  
☐ Other \_\_\_\_\_

If Yes: Estimated Volume (Cubic Yards) \_\_\_\_\_

Name of Licensed Disposal Facility or COGCC Facility ID # \_\_\_\_\_

☐ Excavate and onsite remediation

☐ Land Treatment  
☐ Bioremediation (or enhanced bioremediation)  
☐ Chemical oxidation  
☐ Other \_\_\_\_\_

### **Groundwater Remediation Summary**

☐ No Bioremediation ( or enhanced bioremediation )

☐ No Chemical oxidation

☐ No Air sparge / Soil vapor extraction

☐ Yes Natural Attenuation

☐ No Other \_\_\_\_\_

### **GROUNDWATER MONITORING**

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

Five initial groundwater monitoring wells were installed during assessment activities. Groundwater monitoring will occur on a quarterly basis and groundwater samples will be collected for analysis of BTEX, naphthalene, 1,2,4-trimethylbenzene, 1,3,5-trimethylbenzene, and inorganic parameters. Replacement monitoring wells will be installed.

## REMEDIATION PROGRESS UPDATE

### PERIODIC REPORTING

#### Approved Reporting Schedule:

☒ Quarterly☐ Semi-Annually☐ Annually☐ Other

#### ☐ Request Alternative Reporting Schedule:

☐ Semi-Annually☐ Annually☐ Other

Rule 913.e:

After initial approval of a Form 27, the Operator will provide quarterly update reports in a Supplemental Form 27 to document progress of site investigation and remediation, unless an alternative reporting schedule has been requested by the Operator and approved by the Director. The Director may request a more frequent reporting schedule based on site-specific conditions.

#### Report Type:

☒ Groundwater Monitoring☐ Land Treatment Progress Report☐ O&M Report☐ Other

### Adequacy of Operator's General Liability Insurance and Financial Assurance

Describe the adequacy of the Operator's general liability insurance and Financial Assurance to fully address the anticipated costs of Remediation, including the estimated remaining cost for this project (below).

If this information has been provided on a Form 27 within the last 12 months, provide the Document Number of that form.

The General Liability coverage within the Civitas Resources insurance program includes coverage for bodily injury, property damage, and pollution clean-up costs arising from qualifying pollution events of a sudden and accidental nature subject to a \$1,000,000 per occurrence limit and \$2,000,000 aggregate limit. The Civitas Resources insurance program includes Excess Liability coverage of \$110,000,000 per occurrence and in the aggregate which sits over the sudden and accidental pollution within the General Liability coverage. It is the opinion of Civitas Resources that this total tower of limit is adequate to address the costs of remediation associated with any qualifying pollution event.

Operator anticipates the remaining cost for this project to be: \$ 75000

### WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? No

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards

E&P waste (solid) description

COGCC Disposal Facility ID #, if applicable:

Non-COGCC Disposal Facility:

Volume of E&P Waste (liquid) in barrels

E&P waste (liquid) description

COGCC Disposal Facility ID #, if applicable:

Non-COGCC Disposal Facility:

## REMEDIATION COMPLETION REPORT

### REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? No

If YES:

☐ Compliant with Rule 913.h.(1).

☐ Compliant with Rule 913.h.(2).

☐ Compliant with Rule 913.h.(3).

Do all soils meet Table 915-1 standards? No

Does the previous reply indicate consideration of background concentrations? \_\_\_\_\_

Does Groundwater meet Table 915-1 standards? Yes \_\_\_\_\_

Is additional groundwater monitoring to be conducted? \_\_\_\_\_

Operator shall comply with the COGCC 1000-Series Reclamation Requirements for all impacted and disturbed areas.

## RECLAMATION PLAN

### RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

Reclamation will be in accordance with COGCC 1000 series rules. A detailed reclamation plan may be submitted to account for pH, SAR, and EC.

Is the described reclamation complete? No \_\_\_\_\_

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

☐ Interim

☐ Final

Did the Surface Owner provide the seed mix? \_\_\_\_\_

If YES, does the seed mix comply with local soil conservation district recommendations? \_\_\_\_\_

Did the local soil conservation district provide the seed mix? \_\_\_\_\_

### SITE RECLAMATION DATES

Proposed date of commencement of Reclamation. \_\_\_\_\_

Proposed date of completion of Reclamation. \_\_\_\_\_

## IMPLEMENTATION SCHEDULE

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

### PRIOR DATES

Date of Surface Owner notification/consultation, if required. 09/14/2021

Actual Spill or Release date, or date of discovery. 09/14/2021

### SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 10/08/2021

Proposed site investigation commencement. 10/08/2021

Proposed completion of site investigation. 06/30/2023

### REMEDIAL ACTION DATES

Proposed start date of Remediation. 03/01/2022

Proposed date of completion of Remediation. 11/30/2023

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

☒ Change from approved implementation schedule per Rule 913.d.(2).

Basis for change in implementation schedule:

A proposed remediation completion date will be provided once a full site assessment is completed and data is reviewed.

**OPERATOR COMMENT**

--

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Jacob Evans

Title: Environmental Advisor

Submit Date: 07/03/2023

Email: jevans@civiresources.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: Kari Brown

Date: 08/28/2023

Remediation Project Number: 21354

**COA Type****Description**

0 COA	

**Attachment Check List**

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

**Att Doc Num****Name**

403452166	FORM 27-SUPPLEMENTAL-SUBMITTED
403452171	MONITORING REPORT

Total Attach: 2 Files

**General Comments****User Group****Comment****Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)