

Federal 11-90-26 #1 —API—051-06060

Inspection Doc -708300780—8/14/2023

CA #1 of 1—Check dams on lease road leading to location are full of sediment





Federal 11-90-26 #1 —API—051-06060

Inspection Doc -708300780

CA #1 of 1—Check dams cleaned out and maintained 8/24/23





Federal 11-90-26 #1 —API—051-06060

Inspection Doc -708300780

CA #1 of 1—Check dams cleaned out and maintained 8/24/23

