



WELL SITE INSPECTION FORM
(DRILLING AND PLUGGING)

6

Well Name: Coeyburn 1-21 API Number 05-009-5096
 Operator: Horizon O+G Permit # _____
 Location: NWSE 21-335-42W County: BACA
 Field: _____ Inspector: ZBB

AL/PA/DA Inspection Results: Well Status:
 Pass(Y) _____ Fail(N) Date 11-14-91 ND _____ DG _____ WO _____ PR _____ SI _____ TA _____

Date of Inspection Before/During Drilling _____

Surf. Csg. Size _____ Setting Depth _____ Cmt. Vol. _____ WOC time _____
 Consistent with APD casing Program? YES _____ NO _____ Returns _____
 Rig _____ BOP'S _____ Stage Tool Depth _____ Cmt. Vol. _____

Date of Inspection Before/During/After Completion _____

Prod. Csg. Set? _____ Completion Rig/Activity _____
 Drilling Pits: Closed _____ Open _____ Wellhead Installed: _____ Sign: Yes _____ No _____
 Tank ID: Yes _____ No _____ N/A _____ Skim Tank/Pit: _____ Prod. Tanks: () _____ BBLs
 Equipment _____ Meter Run: Yes _____ No _____
 Bradenhead Press: _____ Fluid: No _____ Yes _____ Type _____ Well Cat. _____

AL/PA/DA Inspection

Date Plugged: 9-9-91 Date Permit Expired: _____
 Hole Plugged: Yes No _____ Pits Backfilled: Yes No
 Material Buried: Yes _____ No N/A _____ Site Clean: Yes _____ No
 Bond Release OK: Yes _____ No Fed _____ Hole Marker: Yes _____ No

Date of Safety/Status Inspection _____

Comments: GM, broken tank, repairs

Violations: Yes _____ No Notice Sent: Yes _____ No _____ Date Sent: _____