

WELL SITE INSPECTION FORM
(DRILLING AND PLUGGING)



00595225

6

Well Name Cogburn 1-21 API Number 05 - 009 - 5096
Operator Horizon Permit # _____
Location NWSE 21- 335- 42W County BACA
Field _____ Inspector EBB

AL/PA/DA Inspection Results:

Well Status:

Pass(Y) X Fail(N) ? Date 7-29-92 ND _____ DG _____ WO _____ PR _____ SI _____ TA _____

Date of Inspection Before/During Drilling _____

Surf. Csg. Size _____ Setting Depth _____ Cmt. Vol. _____ WOC time _____
Consistent with APD casing Program? YES _____ NO _____ Returns _____
Rig _____ BOP'S _____ Stage Tool Depth _____ Cmt. Vol. _____

Date of Inspection Before/During/After Completion _____

Prod. Csg. Set? _____ Completion Rig/Activity _____
Drilling Pits: Closed _____ Open _____ Wellhead Installed: _____ Sign: Yes _____ No _____
Tank ID: Yes _____ No _____ N/A _____ Skim Tank/Pit: _____ Prod. Tanks: () _____ BBLs
Equipment _____ Meter Run: Yes _____ No _____
Bradenhead Press: _____ Fluid: No _____ Yes _____ Type _____ Well Cat. _____

AL/PA/DA Inspection

Date Plugged: 9-9-91 Date Permit Expired: _____
Hole Plugged: Yes ✓ No _____ Pits Backfilled: Yes ✓ No _____
Material Buried: Yes ✓ No _____ N/A _____ Site Clean: Yes ✓ No _____
Bond Release OK: Yes _____ No ✓ Fed _____ Hole Marker: Yes _____ No _____

Date of Safety/Status Inspection _____

Comments: Broken and bent tank left at site near farm junkyard
Gas meter run on site

Site plowed

Violations: Yes _____ No _____ Notice Sent: Yes _____ No _____ Date Sent: _____