

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/24/2023

Submitted Date:

08/30/2023

Document Number:

707601745

FIELD INSPECTION FORM

Loc ID 436284	Inspector Name: Evins, Bret	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 14 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: 69175 Name of Operator: PDC ENERGY INC Address: 1099 18TH STREET SUITE 1500 City: DENVER State: CO Zip: 80202				
ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE				

Contact Information:			
Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	All Inspections

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
436282	WELL	PR	06/01/2023	OW	123-39038	Chesnut 28M-423	SI
436283	WELL	PR	06/01/2015	OW	123-39039	Chesnut 28M-323	PR
436286	WELL	PR	06/01/2015	OW	123-39040	CHESNUT 28R-243	PR
436287	WELL	PR	06/01/2015	OW	123-39041	Chesnut 28R-443	PR
436288	WELL	SI	02/01/2023	OW	123-39042	Chesnut 28M-203	SI

General Comment: This is a WELL inspection. Well(s): 3: Producing PR ; 2: Shut-In SI. Battery: Active. Centralized Battery serves 1 Location ID (436284). (Well(s): 3: Producing PR ; 2: Shut-In SI.). Centralized Battery serves 1 Tank Battery Facility ID (Pending). Reference: Field Inspection Report doc. #707601748 and/or Location ID #436284 for Battery / Facility, Equipment info.

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	5: Wellsites.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	5: Wellsites. Iron panel.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 5		
Comment:	5: Wellsites.		
Corrective Action:		Date:	
Type: Bradenhead	# 5		
Comment:	5: Wellsites. Appears plumbed to surface.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.376887,-104.549505
Comment:	Centralized Battery serves 1 Location ID (436284). (Well(s): 3: Producing PR ; 2: Shut-In SI.). Centralized Battery serves 1 Tank Battery Facility ID (Pending).				
Corrective Action:					Date:

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 436282 Type: WELL API Number: 123-39038 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: PRODUCTION RECORDSComment: Shut-In | SI.
Observed prod. valves shut.
CECMC records last prod: 02/2023.Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 02/01/2023 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action: Date: Facility ID: 436283 Type: WELL API Number: 123-39039 Status: PR Insp. Status: PR**Producing Well**Comment: Producing | PR.Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 08/11/2023 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action: Date: Facility ID: 436286 Type: WELL API Number: 123-39040 Status: PR Insp. Status: PR**Producing Well**Comment: Producing | PR.Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 08/11/2023 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action: Date: Facility ID: 436287 Type: WELL API Number: 123-39041 Status: PR Insp. Status: PR**Producing Well**Comment: Producing | PR.

Corrective Action:	Date:
<u>BradenHead</u>	
Date of Last Brhd Test: <u>08/11/2023</u> Annual Brhd Completed? <u>Yes</u>	
Last Brhd Test Results Initial Surf Csg Pressure: <u>18</u> Fluid Type: _____	
End Surf Csg Pressure: <u>0</u>	
Comment: _____	
Corrective Action: _____	Date: _____

Facility ID: <u>436288</u>	Type: <u>WELL</u>	API Number: <u>123-39042</u>	Status: <u>SI</u>	Insp. Status: <u>SI</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

<u>Idle Well</u>	
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: <u>PRODUCTION RECORDS</u>	
Comment: <u>Shut-In SI.</u> <u>Observed prod. valves shut.</u> <u>CECMC records last prod: 01/2023.</u>	
Corrective Action: _____	Date: _____

<u>BradenHead</u>	
Date of Last Brhd Test: <u>02/01/2023</u> Annual Brhd Completed? <u>Yes</u>	
Last Brhd Test Results Initial Surf Csg Pressure: <u>0</u> Fluid Type: _____	
End Surf Csg Pressure: <u>0</u>	
Comment: _____	
Corrective Action: _____	Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>CECMC Inspection Report Summary:</p> <p>On THU 08/24/2023 at approximately 15:59 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: PDC ENERGY INC Location Name: Chesnut/28M-HZ Pad Location ID: 436284 Well Name(s): Chesnut 28M-423, Chesnut 28M-323, Chesnut 28R-243, Chesnut 28R-443, Chesnut 28M-203. API: 123-39038, 123-39039, 123-39040, 123-39041, 123-39042. Location County: Weld County, Colorado Weather: Mostly Sunny, some wet areas from prior storm.</p> <p>While there, I observed: Well(s): 3: Producing PR ; 2: Shut-In SI. Battery: Active.</p> <p>Centralized Battery serves 1 Location ID (436284). (Well(s): 3: Producing PR ; 2: Shut-In SI.).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (Pending).</p> <p>Reference: Field Inspection Report doc. #707601748 and/or Location ID #436284 for Battery / Facility, Equipment info.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	08/26/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707601746	Site photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6237756