

**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC N7E Pad**  
**Location #: 324006**



**Photo # 7263 From entrance to location**




**Photo # 7264 Location**



**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC N7E Pad**  
**Location #: 324006**



**Photo # 7265 Location**



**Photo # 7266 Location**



**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC N7E Pad**  
**Location #: 324006**



**Photo # 7269 Debris**



**Photo # 7270 Debris**



**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC N7E Pad**  
**Location #: 324006**



**Photo # 7271 Debris**



**Photo # 7277 Weeds/undesirable plant species**



**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC N7E Pad**  
**Location #: 324006**



**Photo # 7280 Weeds/undesirable plant species**



**Photo # 7282 Weeds/undesirable plant species**