



Work Completion Report

Completion Header

Location Completed	HSR-DEKALB-62N65W_28NESE
Alt Loc Name	HSR-DEKALB-62N65W_28NESE
Visited On	08/16/2023
Performed By	Peerless
One-Call Number	
Red Zone Date	
Red Zone APC Rep	

Location Details

Location	HSR-DEKALB-62N65W_28NESE
Location Type	Regulatory
Land Use - Insp	Pasture
Crop Type	
Latitude/Longitude	40.105060/-104.665200
Legal Address	(WELD) SWSE 28 2N65W
COGCC Loc ID	332963
Land Rep	
Road Directions	CR 47 & CR 16, W. 2.04 MI, AT BATTERY NW. 3/10 MI INTO.
Land Use - Loc	Pasture
Rec Contractor PO(s)	
Vendor PO(s)	



Work Completion Report

Work Completion Details

Assoc Work Task	Stormwater Repairs
Assoc Job	ALLEN 9-29A
Work Summary	Repaired erosion on eastern and northern portions of the pad. Fixed rills that where on site.
SqFtAffected	
AcresAffected	0.10000
Seed Mix	None used
LandUse	Pasture
CropType	
SoilType	Clay Loam
CompletionDate	8/16/2023 12:00:00 AM
StabilizationDate	8/16/2023 12:00:00 AM
SeedingDate	
Mulch	None
Straw Bales	
SoilAmendType	None
SoilAmendUnits	
SoilAmendAmount	
SoilAmendRate	NA
Top Soil	NA
Topsoil Source	
General Notes	



Work Completion Report

Work Task Details

Work Task	Stormwater Repairs
Job	ALLEN 9-29A
Requested On	7/17/2023 12:00:00 AM
Requested By	Tyler Scherden
Did COGCC issue a CA for Work?	No
Start By Date	
Due By Date	
Recur Frequency	
Status	Completed
Notes	Erosion repairs on eastern and northern portions of the pad.



Work Completion Report

Photos

Photo Type	General
Photo Name	Allen 2
Photo Notes	
PhotoBlobID	



Work Completion Report





Work Completion Report

Photo Type General

Photo Name Allen 3

Photo Notes

PhotoBlobID





Work Completion Report

Photo Type

Post-Completion

Photo Name

Post-Completion

Photo Notes

PhotoBlobID





Work Completion Report

Photo Type

Pre-Completion

Photo Name

Pre-Completion

Photo Notes

PhotoBlobID





Work Completion Report

Photo Type

Site Map

Photo Name

Site Map

Photo Notes

PhotoBlobID





Work Completion Report
