



Work Completion Report

Completion Header

Location Completed	POWERS_30N-27HZ
Alt Loc Name	POWERS_30N-27HZ
Visited On	08/16/2023
Performed By	Peerless
One-Call Number	
Red Zone Date	
Red Zone APC Rep	

Location Details

Location	POWERS_30N-27HZ
Location Type	Regulatory
Land Use - Insp	Pasture
Crop Type	
Latitude/Longitude	40.103720/-104.657345
Legal Address	(WELD) SWSW 27 2N65W
COGCC Loc ID	430972
Land Rep	
Road Directions	CR 47 & CR 16, W. 2.0 MI, AT INTERSECTION NE. 0.03 MI, E. 0.27 MI, N. 0.18 MI INTO.
Land Use - Loc	Pasture
Rec Contractor PO(s)	
Vendor PO(s)	



Work Completion Report

Work Completion Details

Assoc Work Task	Stormwater Repairs
Assoc Job	POWERS 4C-27HZ
Work Summary	Repaired erosion throughout multiple areas of the location.
SqFtAffected	
AcresAffected	0.25000
Seed Mix	None used
LandUse	Pasture
CropType	
SoilType	Sandy Loam
CompletionDate	8/16/2023 12:00:00 AM
StabilizationDate	8/16/2023 12:00:00 AM
SeedingDate	
Mulch	None
Straw Bales	
SoilAmendType	None
SoilAmendUnits	
SoilAmendAmount	
SoilAmendRate	NA
Top Soil	NA
Topsoil Source	
General Notes	



Work Completion Report

Work Task Details

Work Task	Stormwater Repairs
Job	POWERS 4C-27HZ
Requested On	8/3/2023 12:00:00 AM
Requested By	Tyler Scherden
Did COGCC issue a CA for Work?	Yes
Start By Date	
Due By Date	
Recur Frequency	
Status	Completed
Notes	Repair erosion at multiple locations on battery pad.



Work Completion Report

Photos

Photo Type	General
Photo Name	Powers
Photo Notes	
PhotoBlobID	





Work Completion Report

Photo Type

Post-Completion

Photo Name

Post-Completion

Photo Notes

PhotoBlobID





Work Completion Report

Photo Type

Pre-Completion

Photo Name

Pre-Completion

Photo Notes

PhotoBlobID





Work Completion Report

Photo Type

Site Map

Photo Name

Site Map

Photo Notes

PhotoBlobID

